

Comments:

In Fig. 3, there are four tanks (10) shown at the top of the figure. Each of these tanks shows, by arrows, fluid entering on the left and leaving on the right from the bottom of the tank. However, in the second tank from the left the fluid is to enter on the right and leave on the left, and this has been amended in the revised figure 3. This is a drafting error where the arrow senses were inadvertently reversed.

Also, in figure 3, the conduit that extends from the top of the third tank from the left (identified by numeral 10), this conduit terminates shy of its "T" connector which is shown just below the terminal end of this conduit. This has been corrected in this amendment by extending this conduit to connect to the "T" connector, which is shown just below. Again, this is a drafting error where the drafter failed to make connection to the "T" connector.

A replacement sheet showing the corrected figure 3 is enclosed, as well as a red line version showing the corrections. The reference numerals and leader lines have been formalized in all figures.

Respectfully submitted,



Gene Scott, Reg. No.: 37,930

Patent Law & Venture Group
3140 Red Hill Avenue, Suite. 150
Costa Mesa, CA 92626-3440
Telephone: Phone: (714) 668-1900

Certification

I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelope addressed to: "Mail Stop: Non-Fee Amendment, Commissioner For Patents, PO Box 1450, Alexandria, VA 22313-1450," on 10/6/03 date of deposit.

Signature: 
Person Mailing This Document

REO - LINE CORRECTIONS

Awad.A-09

3/3




Fig. 3